

基準点測量 高低角補正計算

| | | | | | | |
|-----------------------|----------------|----------------|-----------------|--------------|--|--|
| 器械点 A-R2 反射点 B-R5 | m | m | | | | |
| | i1 = 1.595 | g = 1.595 | | | | |
| | i2 = 1.572 | m = 1.539 | | | | |
| | f1 = 1.663 | D = 39.370 | | | | |
| | f2 = 1.539 | | | | | |
| | ° | ° | ° | m | | |
| | A1 = - 3 57 20 | x1 = 0 0 0 | A1' = - 3 57 20 | dh1 = -2.660 | | |
| | A2 = + 4 0 8 | x2 = - 0 3 3 | A2' = + 3 57 5 | dh2 = 2.657 | | |
| | | | Am = - 3 57 13 | = -0.003 | | |
| 器械点 B-R1 反射点 B-R2 | m | m | | | | |
| | i1 = 1.563 | g = 1.563 | | | | |
| | i2 = 1.579 | m = 1.583 | | | | |
| | f1 = 1.562 | D = 51.780 | | | | |
| | f2 = 1.583 | | | | | |
| | ° | ° | ° | m | | |
| | A1 = -10 54 18 | x1 = 0 0 0 | A1' = -10 54 18 | dh1 = -9.816 | | |
| | A2 = +10 53 51 | x2 = - 0 0 12 | A2' = +10 53 39 | dh2 = 9.806 | | |
| | | | Am = -10 53 59 | = -0.010 | | |
| 器械点 B-R2 反射点 B-R12 | m | m | | | | |
| | i1 = 1.579 | g = 1.579 | | | | |
| | i2 = 1.500 | m = 1.593 | | | | |
| | f1 = 1.500 | D = 34.700 | | | | |
| | f2 = 1.593 | | | | | |
| | ° | ° | ° | m | | |
| | A1 = - 8 52 29 | x1 = 0 0 0 | A1' = - 8 52 29 | dh1 = -5.367 | | |
| | A2 = + 8 53 13 | x2 = - 0 1 22 | A2' = + 8 51 51 | dh2 = 5.361 | | |
| | | | Am = - 8 52 10 | = -0.006 | | |
| 器械点 B-R3 反射点 B-R11 | m | m | | | | |
| | i1 = 1.580 | g = 1.580 | | | | |
| | i2 = 1.500 | m = 0.100 | | | | |
| | f1 = 1.500 | D = 31.563 | | | | |
| | f2 = 0.100 | | | | | |
| | ° | ° | ° | m | | |
| | A1 = - 9 12 11 | x1 = 0 0 0 | A1' = - 9 12 11 | dh1 = -3.568 | | |
| | A2 = + 6 31 30 | x2 = + 2 40 13 | A2' = + 9 11 43 | dh2 = 3.564 | | |
| | | | Am = - 9 11 57 | = -0.004 | | |
| 器械点 B-R3 反射点 B-R6 | m | m | | | | |
| | i1 = 1.580 | g = 1.580 | | | | |
| | i2 = 1.500 | m = 1.593 | | | | |
| | f1 = 1.500 | D = 52.732 | | | | |
| | f2 = 1.593 | | | | | |
| | ° | ° | ° | m | | |
| | A1 = - 3 52 29 | x1 = 0 0 0 | A1' = - 3 52 29 | dh1 = -3.576 | | |
| | A2 = + 3 52 57 | x2 = - 0 0 51 | A2' = + 3 52 6 | dh2 = 3.571 | | |
| | | | Am = - 3 52 18 | = -0.005 | | |

基準点測量 高低角補正計算

| | | | | | | |
|-----------|----------------|----------------|-----------------|--------------|---|---|
| 器械点 A-R3 | m | | m | | | |
| | i1 = 1.715 | | g = 1.715 | | | |
| 反射点 B-R7 | i2 = 1.500 | | m = 1.500 | | | |
| | f1 = 1.500 | | D = 38.663 | | | |
| | f2 = 1.500 | | | | | |
| | ° | | ° | | ° | m |
| | A1 = - 9 37 23 | x1 = 0 0 0 | A1' = - 9 37 23 | dh1 = -6.248 | | |
| | A2 = + 9 18 20 | x2 = + 0 18 52 | A2' = + 9 37 12 | dh2 = 6.246 | | |
| | | | Am = - 9 37 18 | = -0.002 | | |
| 器械点 B-R13 | m | | m | | | |
| | i1 = 1.500 | | g = 1.500 | | | |
| 反射点 B-R14 | i2 = 1.500 | | m = 0.300 | | | |
| | f1 = 1.500 | | D = 40.908 | | | |
| | f2 = 0.300 | | | | | |
| | ° | | ° | | ° | m |
| | A1 = - 5 1 54 | x1 = 0 0 0 | A1' = - 5 1 54 | dh1 = -2.388 | | |
| | A2 = + 3 21 44 | x2 = + 1 40 41 | A2' = + 5 2 25 | dh2 = 2.394 | | |
| | | | Am = - 5 2 10 | = 0.006 | | |
| 器械点 B-R20 | m | | m | | | |
| | i1 = 1.730 | | g = 1.730 | | | |
| 反射点 B-R21 | i2 = 1.500 | | m = 1.500 | | | |
| | f1 = 1.500 | | D = 43.529 | | | |
| | f2 = 1.500 | | | | | |
| | ° | | ° | | ° | m |
| | A1 = + 5 11 14 | x1 = 0 0 0 | A1' = + 5 11 14 | dh1 = 4.166 | | |
| | A2 = - 5 29 48 | x2 = + 0 18 5 | A2' = - 5 11 43 | dh2 = -4.171 | | |
| | | | Am = + 5 11 29 | = -0.005 | | |